Radiance Mounting Template

Directions for using this template:

1. Start at the location for the top hole # 1 on the diagram.

2. Use a level or a weighted string to determine a true vertical line descending from that point.

3. Measure vertically down that line to point #2.

4. Use a level or a square to establish a horizontal line at that point.

5. Measure along that line to point 3. This will be the second screw hole.

6. Temporarily install the sculpture using those two points. Mark the other mounting holes with the sculpture in place.

7. Remove the sculpture. Install the appropiate anchors and permanently

