

## SoloMounting Template

Directions for using this template:

1. Start at the location for the top hole # 1 on the diagram. Notice the clearance requirements from left to right.
2. Use a level or a weighted string to determine a true vertical line descending from that point. Precise level is important.
3. Measure vertically down that line to point #2.
4. Use a level or a square to establish a horizontal line at that point.
5. Measure along that line to point 3.
6. Temporarily install the sculpture using those two points. Mark the other mounting holes with the sculpture in place.
7. Remove the sculpture. Install the appropriate anchors and permanently remount the sculpture on the wall.

