



# Variation Mounting Template

Directions for using this template:

1. Start at the location for the top hole # 1 on the diagram. It is for the top screw hole of the base piece of the winding portion.
2. Use a level or a weighted string to determine a true vertical line descending from that point. Precise level is important.
3. Measure vertically down that line to point #3.
4. Use a level or a square to establish a horizontal line at that point.
5. Measure along that line to points 3, 4, 5 marking all.
6. Again using a level or a weighted string measure up to mark holes 6 and 7 which are for the base behind the patterning wheel.
7. Temporarily install the both base parts of the sculpture using those points. Mark the other mounting holes with the sculpture in place.
7. Remove the sculpture. Install the appropriate anchors and permanently remount the sculpture on the wall.



Level along this line

