



Serpentine Mounting Template

Directions for using this template:

Green dotted line are the measurement lines to locate holes.

Blue arrow lines indicate distance from green dotted lines needed for clearance when sculpture is in motion.

Red Arrows point to the places you will need to mark for proper mounting.

1. Start at the location for the top hole # 1 on the diagram. This will be where the top mounting hole in the sculpture is located. Make sure you have proper clearance. There must be 15 1/2" above the top hole.
2. Use a level or a weighted string to determine a true vertical line descending from that point.
3. Measure 10 1/2" vertically down that line to point #2. Mark that lightly. It will show later so mark on a piece of painter's tape.
4. Use a level or a square to establish a horizontal line at that point.
5. Measure along that line 16 1/8" to point 3. Mark that point.
6. Temporarily install the sculpture using those two points.
7. Mark the other mounting hole(s) with the sculpture in place.
8. Remove the sculpture. Install the appropriate anchors in all screw holes and permanently remount the sculpture on the wall. Use 1 1/2" # 8 screws.